



ДИРЕКТИВА ЛЬОТНОЇ ПРИДАТНОСТІ - ТЕРМІНОВА
AIRWORTHINESS DIRECTIVE – EMERGENCY

ДЕРЖАВНА АВІАЦІЙНА СЛУЖБА УКРАЇНИ
(ДЕРЖАВІАСЛУЖБА)

01135, Україна, Київ, пр.Перемоги, 14
тел.: + 380 (44) 461-55-31
факс: + 380 (44) 216-85-39
<http://www.avia.gov.ua>

STATE AVIATION ADMINISTRATION
OF UKRAINE

14, Peremogy ave., 01135, Kyiv, Ukraine
phone: + 380 (44) 461-55-31
fax: + 380 (44) 216-85-39
E-mail: AD-coordinator@avia.gov.ua

Date: 29 June 2017

DLP – 0889T-17

This Airworthiness Directive is issued by the State Aviation Administration of Ukraine in accordance with the Aviation Regulations of Ukraine, part 21, section A, subpart A, 21.A.3B «Airworthiness Directives»

Design (Change) Approval Holder's Name:

Antonov Company

Type/Model designation(s):

An-74 (Antonov-74); Antonov-72-100

TCDS Number: ГЛ 0009, ГЛ 0028

Foreign AD: not applicable

Supersedure: not applicable

Effective Date: 29 June 2017

ATA Nr. – ATA Chapter Name – Part / System Name – Required Action(s)

ATA 71 – Power plant – Mounting points – Inspection

Manufacturer(s): KSAMC

Applicability: An-74 (Antonov-74), An-74T (Antonov-74T), An-74D (Antonov-74D), An-74T-100 (Antonov-74T-100), An-74T-200A (Antonov-74T-200A), An-74-200 (Antonov-74-200), An-74TK-100 (Antonov-74TK-100), An-74TK-200 (Antonov-74TK-200), Antonov-72-100, Antonov-72-100D

Reason: On 23 June 2017 at the beginning of take-off run (first 20 meters) of Antonov -74TK-200 airplane, serial number 15-06, there was an unintended drop of the right engine rate from the take-off mode to the lowered. In the future, during inspection, a destruction of the engine thrust link 72.04.6402.919.000 on the rear support and destruction of both mounting brackets 72.04.6402.920.000 on the left and right front supports were revealed.

Required Action(s) and Compliance Time(s):

- before the next flight of the airplane to perform one-time inspection of the engine mounts condition according to ТК601 розд. 071.20.00.РЭ (Aircraft Maintenance Manual);
- in case of damage finding, inform airplane designer – Antonov Company and State Aviation Administration of Ukraine.

Ref. Publications: ТК601 розд. 071.20.00.РЭ

Remarks: reserved

The Airworthiness Directive original in Ukrainian language is signed by S. Korshuk, Acting Chairman of the State Aviation Administration of Ukraine